

City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 1 of 1

Sewershed: Gwynns Falls

Company: Savin

Date: 7/7/2009

Test to be performed:

Smoke ☐ Dyed Water ☒

Ground Condition:

Dry ☒ Damp ☐ Wet ☐

Supervisor: JAW

Manhole_ID: S07SS_032MH

Test ID: D1032-015004

Notification Made: NA

(Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S07SS_012MH
0			Water Level	
40.90000153	02		Tap Factory Defective	FROM 3606, B, JOL
40.90000153			Dye Test Visible	@ TFD - FROM DOWN SPOUT IN BACK
40.90000153			General Observation	NO ROOF GUTTER IS HOOKED TO THIS
40.90000153			Manhole	S07SS_032MH
40.90000153			End of Survey	TEST COMPLETED
70	02		Tap Factory Capped	